

## Discontinued Compressors DLX, DLE, DLY, TLX, TLY Discontinued NLY Range

Secop would like to announce that compressor models **DLX-KK/KK.1**, **DLE-KK**, **DLY-KK**, and **TLX-KK/KK.3**, **TLY-F/FK.2/KTK/KK.3** will be discontinued in 2022.

Older NLY models for the refrigerants R134a and R600a have already been phased out.

Secop would like to reinforce its commitment to concentrating its efforts and investments into core businesses of stationary and mobile refrigeration, while striving to maintain our leadership in these key market segments.

These platforms no longer fit the core strategic focus of the company.

## Phase-out Date and Code Numbers

The above-mentioned compressor platforms will reach their end of life (EOL) soon. Current customers can place their final orders until the end of October 2021.

The table on the right side shows all code numbers affected incl. variants and customer specific types.

## Replacement Solution

Secop is committed to supporting its customers during this transition to migrate to alternative solutions (e.g. K-Series compressors).

## Further Info

Please get in touch with your local Secop representative for further information or replacement solutions.

Visit: <https://www.secop.com/products/end-of-life> to find data sheets for standard types.

Platform	Code Number	Compressor	Single Pack Code Number
DLX	102H3453	DLX4KK	n/a
	102H3456	DLX4KK	n/a
	102H3457	DLX4KK	n/a
	102H3459	DLX4KK.1	n/a
	102H3552	DLX4.8KK	n/a
	102H3553	DLX4.8KK	n/a
	102H3555	DLX4.8KK.1	n/a
	102H3558	DLX4.8KK.1	n/a
	102H3559	DLX4.8KK.1	195B4281
	102H3659	DLX5.7KK.1	n/a
	102H4159	DLX9.4KK.1	n/a
	102H4599	DLX4.8KK	n/a
	102H4659	DLX5.7KK	n/a
	102H4691	DLX5.7KK.1	n/a
	102H4810	DLX7.5KK	n/a
	102H4854	DLX7.5KK.1	n/a
	102H4889	DLX7.5KK	n/a
	102H4895	DLX7.5KK	n/a
	102H4896	DLX7.5KK	n/a
	102H4982	DLX8.7KK.1	n/a
102H4988	DLX8.7KK	n/a	
102H4990	DLX8.7KK.1	n/a	
102H4999	DLX8.7KK	n/a	
DLE	102H4082	DLE10KK	n/a
	102H4084	DLE10KK	n/a
	102H4820	DLE7.5KK	n/a
	102H4950	DLE8.7KK	n/a
	102H4952	DLE9.4KK	n/a
DLY	102H4086	DLY10KK	n/a
TLX	102H4447	TLX4KK.3	195B3273
	102H4477	TLX4KK.3	n/a
	102H4569	TLX4.8KK.3	n/a
	102H4643	TLX5.7KK.3	n/a
	102H4645	TLX5.7KK.3	n/a
	102H4647	TLX5.7KK.3	195B4121
	102H4686	TLX5.7KK.3	n/a
	102H4688	TLX5.7KK.3	n/a
	102H4747	TLX6.5KK.3	195B3260, 195B4287
	102H4776	TLX7KK	n/a
	102H4847	TLX7.5KK.3	195B3183
	102H4947	TLX8.7KK.3	n/a
TLY	102G4480	TLY4F	n/a
	102G4529	TLY5.1FK.2	n/a
	102H3750	TLY6.5KTK	n/a
	102H4042	TLY10KK.3	n/a
	102H4442	TLY4KK.3	n/a
	102H4542	TLY4.8KK.3	195B4261
	102H4641	TLY5.7KK.3	n/a
	102H4642	TLY5.7KK.3	n/a
	102H4742	TLY6.5KK.3	195B4236
	102H4878	TLY7.5KK.3	195B3239

**Secop GmbH**  
Mads-Clausen-Str. 7  
24939 Flensburg  
Germany  
Tel: +49 461 4941 0  
[www.secop.com](http://www.secop.com)

Secop accepts no responsibility for possible errors in catalogs, brochures, and other printed material. Secop reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without consequential changes being necessary to specifications already agreed. All trademarks in this material are the property of the respective companies. Secop and the Secop logotype are trademarks of Secop GmbH. All rights reserved.