

Additional Supplier for 117U7xxx Series Relays

Secop has added a new supplier of current relays: Changshu Tianyin Electromechanical Co., Ltd. to meet the demand of compressor production capacity and ensure the supply.

The performance parameters of relays supplied by Tianyin are the same as the current ones and have no effect on the performance of compressors. The certification (including VDE and CCC) of relays supplied by Tianyin are available.

The long-term reliability test for the relays produced by Tianyin were completed, which were based on operating independently and with compressors. The results indicated conformity with the requirements.

The change is effective from January 30, 2020. The future current relay will be provided by two suppliers.




Fig.1 117U7xxx starting relay manufactured by Secop s.r.o (Slovakia)

Compressors Affected by the Change

Relay Code Number	Compressor Code Number	Compressor Type
117U7013	104H8169	SC21CNX.2
	104H8156	
	104H8159	
	104H8166	
	104H8168	
	104H8169	
117U7003	104H8266	SC12CNX.2
	104H8275	SC12MNX
117U7019	104H8575	SC15MNX
	104H8866	SC18CNX.2
117U7005	104H8075	SC10MNX SC15CNX.2 SC15CNX.2
	104H8556	
	104H8566	
	104H8569	
	104H7271	
117U7020	104H7271	SC12CNX.2
	104H7070	SC10CNX.2




Fig.2 117U7xxx starting relay manufactured by Changshu Tianyin Electromechanical Co., Ltd.